



# APT POWER ENGINEERING (P) LIMITED

( ISO 9001:2015 | OHSAS 45001:2018 | ISO 14001:2015 Certified Company)

Reg. Off / Works: Plot No: 11B, IDA, Phase-II, Patancheru, Hyderabad – 502319, T.S, INDIA.

## REPAIR AND REFURBISHMENT REFERENCE LIST

S. No	Customer	Works executed by APT
1	M/s. Madras Aluminum Company (M/s.Vendanta Group) - Chennai	Dismantling, Blue matching, Repairing of all glands, Governing control valves, nozzle segment Refurbishment and supply of generator bearing of Shanghai make 30 MW TG set and its auxiliaries at Tamilnadu.
2	M/s. My Home Power Ltd Patancheru, Hyderabad.	Dismantling, condition assessment, Refurbishment and Re- location of 20 MW Gas turbine and 9 MW Steam turbine at Patancheru, Hyderabad.
3	M/s. Viraj Power Ltd Tarapur, Maharashtra	Dismantling at DESU, Rajghat, Project Engineering, Repair, Refurbishment including condition assessment, Manufacturing of critical Worn-out components, Erection & Commissioning of LANG BUDAPEST make 15 MW TG set
4	M/s. Usha Martin Ltd, Jamshedpur, Jharkhand	Project Engineering, Repair, Refurbishment including condition assessment, Re-blading of Rotor and casing, manufacturing of critical Worn-out components, Erection & Commissioning of LANG BUDAPEST make 15 MW TG set.
5	M/s. Prakash Industries Ltd, Champa, Chhattisgarh	Repair, Refurbishment, Erection & Commissioning of ENGLISH ELECTRIC make 2 x 7.5 MW TG set.
6	M/s. Penna Electricity Ltd Ramanathapuram, Tamilnadu	Project Engineering, Repair, Refurbishment, Manufacturing of Worn-out components, Erection & Commissioning of SIEMENS make 32 MW TG set.
7	M/s. Ballarpur Industries Ltd Ballarshah, Maharashtra	Repair, Refurbishment including condition assessment, Re-blading of Rotor, Manufacturing of worn-out items, Erection & Commissioning of BROWN BROVERI make 7.5 MW TG set.
8	M/s. Riddhisiddhi Gluco boils Ltd	Repair, Refurbishment including condition assessment, Supply of Servo motor, complete Sr4 governing system & critical worn-out components, Erection & Commissioning of BHEL make 5 MW TG set.



# APT POWER ENGINEERING (P) LIMITED

( ISO 9001:2015 | OHSAS 45001:2018 | ISO 14001:2015 Certified Company)

Reg. Off / Works: Plot No: 11B, IDA, Phase-II, Patancheru, Hyderabad – 502319, T.S, INDIA.

9	M/s. Southern Iron & Steel Co. Ltd, Salem, Tamilnadu	Project Engineering, Repair, Refurbishment including condition assessment, Re-blading of Rotor and casing, manufacturing of critical Worn-out components, Erection & Commissioning of 7.5 MW TG set.
10	M/s. S.V. Sugar Mills Ltd, Tamilnadu.	Repair, Refurbishment including complete condenser re-tubing, Erection & Commissioning of SIEMENS make (HP & IP) 27 MW TG set.
11	M/s. Bilt tube	Repair, Refurbishment, Supply of AOP, EOP and Erection & Commissioning of SIEMENS make 6 MW TG set.
12	M/s. Usha Martin Limited Jamshedpur	Reblading of Rotors, Top casing, Bottom casing, Re-tubing of Ejector, Refining and Erection & Commissioning of LANG BUDAPEST make 15MW TG SET.
13	Zimbabwe power company Harare	HP/LP ROTOR repair, refurbishment ,reblading, retrofit & supply of spares including Turbovisory control panel. Erection & commissioning of Metropolitan Vickers make 30 MW TG Set.
14	M/s.SESA Sterlite Tuticorin, Tamilnadu	Turbine rotor refining, blue matching and Erection & commissioning of BHEL make 80MW TG set.
15	M/s.Penna Cement Industries Limited Miryalaguda, Telangana	Turbine rotor refining Erection & commissioning of HTC make 38.5MW TG set.
16	M/s.Bengal Energy Limited, Kharagpur, WB	Re-analysis of main steam line and modification/ revision of supports and Erection & commissioning of QJPS make 40MW TG set.
17	Thirumalai Chemicals Limited Ranipet	Refurbishment of 5 MW rotor, re-blading, RLA study, High Speed balancing of Rotor
18	Jaibalaji Industries Limited	Refining & Machining of 25 MW Siemens Turbine Rotor, Guide Blade carriers, Front & Rear steam gland & BP gland
19	Prakash Industries	Repair of Rotor & its Components



# APT POWER ENGINEERING (P) LIMITED

( ISO 9001:2015 | OHSAS 45001:2018 | ISO 14001:2015 Certified Company)

Reg. Off / Works: Plot No: 11B, IDA, Phase-II, Patancheru, Hyderabad – 502319, T.S, INDIA.

20	M/s.Gopani Iron & Power India Ltd,Chandrapur,Maharastra	Refining & Machining of Nozzle Chamber & Diaphragms (Stage 1 to 14)
21	M/s.Deccan Cement Ltd, Nalgonda,Telangana	Refining & Machining of 18 MW HTC make Turbine Rotor, Replacement of L Rings
22	M/s.Bengal Energy Limited, Kharagpur, WB	Repair & Replacement of Interstage Diaphragm Nozzle Block
23	M/s.Agarwal Vidyut, Raipur, Chhattisgarh	Repair of diffuser and L- ring along with lock nut, Re-finishing and machining of intermediate stage fins on turbine rotor, front & rear steam gland, carriers and front oil gland
24	M/S.Kalburgi Cement Pvt Ltd, Chincholi,Karnataka	Replacement of control valve cages, Refining and Machining of 30 MW Siemens make Turbine rotor Front Steam Gland, Rear steam gland and BP Gland Fins
25	M/s.SKS Ispat & Power pvt Ltd,Siltara,Raipur	Refining & Machining of 30 MW HTC Turbine Rotor fins & Front steam Gland,Rear Steam Gland,BP Gland & GBC
26	M/s. Heavy water plant, Manuguru	Repair of H2S Gas booster compressor Rotor
27	M/s. Shree Digvijay Cement Co Ltd, Jamnagar, Gujarat	Machining of Turbine Rotor Blades, Front & Rear Journal Polishing, Replacement of control valves and emergency stop valve
28	M/s. Srikalahasthi Pipes Ltd, Chitoor, Andhra Pradesh	Refining & Machining of Diaphragms, Steam Gland ,Nozzle Block & Oil Glands for 7 MW Kaluga make Turbine
29	M/s. Kribco, Surat, Gujarat	Re blading of Boiler feed pump Drive 102-BJT Turbine Rotor
30	M/s. Tata Steel BSL Ltd, Angul, Odhisha	Repair of Coke oven Gas blower Rotor



# APT POWER ENGINEERING (P) LIMITED

( ISO 9001:2015 | OHSAS 45001:2018 | ISO 14001:2015 Certified Company)

Reg. Off / Works: Plot No: 11B, IDA, Phase-II, Patancheru, Hyderabad – 502319, T.S, INDIA.

31	M/s. Jagannath Steels, Odisha	Repair of 30 MW Siemens make Turbine Rotor
32	M/s. Shyam Metalics Ltd, Sambalpur, Odisha	Repair of 30 MW HTC Turbine Rotor and Guide Blade carriers
33	M/s. Shyam Metalics Ltd, Sambalpur, Odisha	Repair of 33 M.W BHEL Make Turbine Rotor, Guide Blade Carriers and Gear box.
34	M/s. Optimistic Organic SDN BHD, Malaysia	Refining & Machining of BP Gland & Front Steam Gland for 9.2 MW Siemens make Turbine Rotor
35	M/s. Tulsyan Nec Limited, Gumidipoondi, Tamilnadu	Refining & Machining of Turbine Rotor Fins, Guide Blade Carriers , Steam Glands for 35 MW (Unit-I) Siemens make Turbine
36	M/s. Top worth Urja & Metals Ltd, Nagpur, Maharastra	Turbine Rotor Journal Machining & Polishing for 30 MW HTC make Turbine
37	M/S.Kalburgi Cement Pvt Ltd, Chincholi, Karanataka	Refining and Machining of 7.5 MW Siemens make Turbine rotor Fins & Guide Blade Carrier Fins
38	M/s. Jayaswal Neco Industries Ltd, Raipur, Chhattisgarh	Refurbishment & Replacement of Turbine & Blower Blades for 6 MW Shanghai make Turbine
39	M/s. Penna Cement Industries Ltd, Nalgonda, Telangana	Rewinding of Complete Generator Rotor for 38.5 MW HTC make Generator
40	M/s.ACC Limited, Chaibasa, Jharkhand	Refining & Machining of Turbine Front & Rear Steam Gland, BP Gland & Turbine & Generator Oil Glands for 15 MW BHEL make Turbine
41	M/s. DSM Sugar Rajpura, Rajpura, Uttar Pradesh	Machining of Thrust Collar and Polishing of 35.5 MW SNM make Turbine Rotor
42	M/s.Dhampur Sugar Mills Ltd, Bijnor, Uttar pradesh	Machining of Thrust Collar & Replacement of Diaphragm Fins for 30 MW SNM make Turbine



# APT POWER ENGINEERING (P) LIMITED

( ISO 9001:2015 | OHSAS 45001:2018 | ISO 14001:2015 Certified Company)

Reg. Off / Works: Plot No: 11B, IDA, Phase-II, Patancheru, Hyderabad – 502319, T.S, INDIA.

43	M/s. Shree Digvijay Cement Co Ltd, Jamnagar, Gujarat	Rewinding of Complete Generator Stator for 9 MW Jinan make Generator
44	M/s. Prakash Industries Ltd, Champa, Chhatisgarh	Replacement of Generator Slip Rings & Refining of Generator Oil Glands for 10 MW Westing House make Generator
45	M/s.Jaibalaji Industries Limited, Burdwan, West Bengal	Refining & Machining of 18 MW Siemens Turbine Rotor Fins, Guide Blade carriers, Replacement of new nozzles with Nozzle Block
46	M/s. Optimistic Organic SDN BHD, Malaysia	Refurbishment of 9 MW Siemens make Turbine Rotor
47	M/s. Thirumalai Chemicals Ltd, Ranipet, Tamilnadu	Removal, procurement and assembly of Turbine Rotor Blades for 1.5 MW Murray make Turbine
48	M/s. Pravara Renewable Energy Ltd, Shridi, Maharastra	Removal, Procurement & Assembly of Turbine LP Stage Blades, Refining of Turbine Rotor, Guide Blade Carriers and All steam Glands for 30 MW Siemens make Turbine
49	M/s.Jaibalaji Industries Limited, Durgapur, West Bengal	Refining & Machining of 35 MW Siemens Turbine Rotor Fins, Guide Blade carriers, Removal of Ovality in Steam Glands
50	M/s. Vedanta Ltd, Sesa Goa, Navelim , Goa	Refining & Machining of 30 MW Siemens Turbine Rotor Fins, Guide Blade carriers & Removal, Procurement & Assembly of Guide Blade Carrier Blades
51	M/s.ACC Limited, Chaibasa, Jharkhand	Refining & Machining of Turbine Front & Rear Steam Gland, BP Gland ,Guide Blade Carriers & Turbine & Generator Oil Glands for 6 MW BHEL make Turbine
52	M/s. Kribco, Surat, Gujarat	Refurbishment of 105-JT Rotors, GBC, Steam Chamber and 104 JT Rotors
53	M/s. Kribco, Surat, Gujarat	Refurbishment of 101-J HP Compressor Rotor
54	M/s.Jaibalaji Industries Limited, Durgapur, West Bengal	Refining & Machining of 25 MW(Unit -I) Siemens Turbine Rotor Fins, Guide Blade carriers, Removal of Ovality in Steam Glands, Repairing of Pinion wheel



# APT POWER ENGINEERING (P) LIMITED

( ISO 9001:2015 | OHSAS 45001:2018 | ISO 14001:2015 Certified Company)

Reg. Off / Works: Plot No: 11B, IDA, Phase-II, Patancheru, Hyderabad – 502319, T.S, INDIA.

55	M/s.Shree Cement Ltd,Beawar,Rajasthan	Refining and Machining of Interstage Diaphragm segments for 50 MW QJPS make Turbine
56	M/s.Suryateja Power Projects Ltd,Gadwal, Telangana	Removal of existing nozzles, manufacturing and assembly of Nozzles in Steam Chest for 6 MW Triveni make Turbine
57	M/s.Suryateja Power Projects Ltd,Gadwal, Telangana	Refining of HP and LP Glands area on Rotor and Thrust collar machining
58	M/s.Jaibalaji Industries Limited, Durgapur, West Bengal	Refining & Machining of 35 MW Siemens Turbine Rotor Fins, Guide Blade carriers, Removal of Ovality in Steam Glands
59	M/s.Greensol power systems Pvt Ltd,Gujarat Cement Works	Refurbishment of Turbine Rotor, GBC, Steam glands, Oil Glands and Top Casing for 23 MW HTC Make Turbine
60	M/s.Shree Cement Ltd,Beawar,Rajasthan	Repairing of Nozzle segments for 25 MW QJPS make Turbine
61	M/s.Shree Cement Ltd,Beawar,Rajasthan	Repair of Turbine Rotor Oil Gland area for 25 MW QJPS make Turbine
62	M/s. Srikalahasthi Pipes Ltd, Chitoor, Andhra Pradesh	Refining & Machining of Diaphragms, Steam Gland ,Nozzle Block & Oil Glands for 7 MW Kaluga make Turbine
62	M/s. Srikalahasthi Pipes Ltd, Chitoor, Andhra Pradesh	Refining & Machining of Diaphragms, Steam Gland ,Nozzle Block & Oil Glands for 12 MW Kaluga make Turbine
63	M/s.TMR Thermo Engineering Industries,Patancheru, Hyderabad	Repair and Reconditioning of Gear Wheel and Pinion shaft
64	M/s. Dalmia Cement Bharat Ltd, Rajganpur, Odhisha	Refining & Machining of 27 MW(Unit-I) Siemens Turbine Rotor Fins & Guide Blade carriers
65	M/s. Dalmia Cement Bharat Ltd, Rajganpur, Odhisha	Refining & Machining of 27 MW(Unit-II) Siemens Turbine Rotor Fins & Guide Blade carriers



# APT POWER ENGINEERING (P) LIMITED

( ISO 9001:2015 | OHSAS 45001:2018 | ISO 14001:2015 Certified Company)

Reg. Off / Works: Plot No: 11B, IDA, Phase-II, Patancheru, Hyderabad – 502319, T.S, INDIA.

66	M/s. Tulsyan Nec Limited, Gumidipoondi, Tamilnadu	Refining & Machining of Turbine Rotor Fins, Guide Blade Carriers , Steam Glands for 35 MW (Unit-II) Siemens make Turbine
67	M/s.Ramagundam fertilizers & Chemicals Ltd, Peddapalli, Telangana	Repair of solution transfer pump 100 P 308
68	M/s. Tata Steel BSL LTD,Angul, Odisha	Refining & Machining of Turbine Rotor Fins, Guide Blade Carriers , Steam Glands for 20 MW Siemens make Turbine
69	M/s.Kamaljeet Singh Ahluwalia,Keonjhar, Odhisha	Refining and Machining of 8 MW Siemens make Turbine Rotor
70	M/s.Greensol power systems Pvt Ltd,Gujarat Cement Works	Refining of Turbine Front Steam Gland and Guide Blade Carrier 6 th Stage for 70 MW HTC Make Turbine
71	M/s.Jayaswal Neco Ltd,Raipur,Chhatisgarh	Refurbishment of WBR fan Impeller
72	M/s.BGR Energy Systems Ltd,	Removal and assembly of LP Stage Blades on TDBFP Shanghai make Turbine Rotor
73	M/s.Jindal Steel & Power Ltd, Angul, Odisha	Repairing of Rotor, Carrier and Glands for 26 MW Shangu make TRT
74	M/s.Hindustan Zinc Ltd,Zawar,Rajasthan	Refining of oil glands for 80 MW BHEL make Turbine
75	M/s.Shree Nakoda Ispat Ltd, Raipur, Chatishgarh	Refining of Diaphragm Gland, Repair of Nozzle Block & Refining of Turbine & Generator oil gland for 12 MW QJPS make Turbine
76	M/s.Vedanta Ltd, Sesa Goa,Goa	Refining of Turbine Rotor for 30 MW SNM make Turbine
77	M/s.Neelachal Ispat Nigam Ltd,Kalinga nagar ,Odisha	Repairing of 13.2 MW SULZER make Steam Turbo Blower Internals & 12 MW Savigliano make ETB



# APT POWER ENGINEERING (P) LIMITED

( ISO 9001:2015 | OHSAS 45001:2018 | ISO 14001:2015 Certified Company)

Reg. Off / Works: Plot No: 11B, IDA, Phase-II, Patancheru, Hyderabad – 502319, T.S, INDIA.

78	M/s.Neelachal Ispat Nigam Ltd,Kalinga nagar ,Odisha	Repairing of 12 MW Savigliano make Electric Turbo Blower Internals
79	M/s.Jindal Saw Ltd, Kutch, Gujarat	Removal, Manufacturing and Assembly of Turbine C Wheel & 1 <sup>st</sup> Stage Blades for 2.12 MW HCTC Turbine
80	M/s.Visa Steel Ltd, Jajpur, Odhisha	Refining of Turbine Rotor, Steam Gland, Guide Blade Carriers and Oil Gland for 25 MW BHEL make Turbine
81	M/s.Thirumalai Chemicals Ltd, Ranipet, Tamilnadu	Repairing of Blower Gearbox Internals for 650 KW Linde make Blower Motor
82	M/s.Jaibalaji Industries Ltd, Burdwan, West Bengal	Polishing & Burnishing of Pinion & Gearwheel shaft for 25 MW Triveni make Gearbox
83	M/s.Sarda Energy Minerals Ltd, Raipur, Chhatisgarh	Refining of oil glands for 36 MW Siemens make Turbine
84	M/s.Lokmangal Mauli Industries Ltd, Lohara, Maharashtra	Refining of Turbine Rotor, Steam Gland, Guide Blade Carriers and Oil Gland for 30 MW BHEL make Turbine
85	M/s.Jindal Saw Ltd, Kutch, Gujarat	Repairing of MOP of 15 MW Triveni make Turbine
86	M/s.Thirumalai Chemicals Ltd, Ranipet, Tamilnadu	Removal, procurement & Assembly of Rotor Blades & C Wheel Disc for 5 MW Murray make Turbine
87	M/s.PT Sulzer, Indonesia	Blades shroud machining of 135 MW Turbine Rotor
88	M/s.Jindal Saw Ltd, Ananthapur, Andhra Pradesh	Refining of Blower Rotor for 3.43 MW Shougan make Blower
89	M/s.Viraj Steel Ltd, Sambalpur, Odhisha	Refining of Turbine Rotor & Steam Glands for 8 MW Triveni make Turbine





# APT POWER ENGINEERING (P) LIMITED

( ISO 9001:2015 | OHSAS 45001:2018 | ISO 14001:2015 Certified Company)

Reg. Off / Works: Plot No: 11B, IDA, Phase-II, Patancheru, Hyderabad – 502319, T.S, INDIA.

90	M/s.KRIBHCO, Surat, Gujarat	Refurbishment of 105 JT Turbine Rotor, Steam Chamber, Nozzle Block & Guide Blade Carrier, Removal, Manufacturing and assembly of Guide Blade Carrier
91	M/s.Murli Industries Ltd, Chandrapur, Maharastra	Refurbishment of 16 MW Triveni make Gearbox
92	M/s.SPS Steels Ltd, Purilia, West Bengal	Refurbishment of 10 MW Triveni make Turbine, Gearbox Internals.
93	M/s.Ramagundam Fertilizer & Chemicals Ltd, Pedapalli, Telangana	Repairing of damaged/seized rotor of "Lean Pump" 100 P 302 A
94	M/s.Bhaskar Steel & Ferro Alloy Ltd,Rourkela, Odhisha	Repairing of HP Steam Gland for 12 MW Triveni Make Turbine
95	M/s.Amalgam Steel & Power Limited, Durg	Repair & Replacement of Control Valve Diffuser for 20 MW BHEL make Turbine
96	M/s.Shreeyam Power & Steel Industries Ltd, Ghandhidam, Gujarat	Refining and Machining of Diaphragm, Nozzle chest & Oil Glands for 30 MW QJPS make Turbine
97	M/s.Heavy Water Plant, Manuguru	Repair of gas compressor rotor, fixing of thrust collar
98	M/s.Ramsarup Industries Ltd, Kharagpur, West Bengal	Repair & Refurbishment of 20 MW HTC make Turbine, Including supply of C wheel to 8 Th stage Turbine Rotor Blades, Refining of Diaphragms
99	M/s.Gopani Iron & Power Steels, Chandrapur	Refining & Machining of Front, Inter stage & Rear Steam Gland segments for 15 MW QJPS make Turbine
100	M/s.Tata Steel Ltd, Angul, Odhisha	Repair & Refurbishment of TRT Generator Rotor
101	M/s.GR Krishna Ferro Alloys Ltd, Chandrapur	Repair of 60 MW HTC make Turbine Rotor, Nozzle segments , Oil Glands & Bearings, Replacement of Fasteners



# APT POWER ENGINEERING (P) LIMITED

( ISO 9001:2015 | OHSAS 45001:2018 | ISO 14001:2015 Certified Company)

Reg. Off / Works: Plot No: 11B, IDA, Phase-II, Patancheru, Hyderabad – 502319, T.S, INDIA.

102	M/s.Electro steel casting ltd, Haldia, West Bengal	Refining of Turbine Rotor & Diaphragms for 12 MW Kaluga make Turbine
103	M/s.GE Power India Ltd, Korba , Chhatisgarh	Auxiliary shaft machining
104	M/s.Dalmia cement bhara tld, Rajgangpur, Odhisha	Repair & Refurbishment of 27 MW Siemens make Turbine
105	M/s.Nava Limited, Paloncha, Telangana	Replacement of 16 <sup>th</sup> Stage moving blades for 32 MW SNM make Turbine
106	M/s.Dalmia cement bhara tld, Rajgangpur, Odhisha	Repair & Refurbishment of 9.2 MW QJPS make Barring gear unit
107	M/s.Dalmia cement bhara tld, Rajgangpur, Odhisha	Refining and machining of 27 MW Siemens make Guide blade carriers
108	M/s.Lloyds Metals & Energy Ltd, Chandrapur	Repair & Refining of 30 MW QJPS make Oil Glands
109	M/s.Electro steel casting ltd, Haldia, West Bengal	Repair of Front & Rear Steam Gland segments for 12 MW Kaluga make Turbine
110	M/s.GE Power India Ltd, Vadodara, Gujarat	Repair & machining of generator shaft ring assembly
111	M/s.Dalmia cement bhara tld, Rajgangpur, Odhisha	Repair & Refurbishment of 9.2 MW QJPS make Barring gear unit
112	M/s.Dalmia cement bhara tld, Rajgangpur, Odhisha	Refining and machining of 27 MW Siemens make Guide blade carriers
113	M/s.Rajshree Sugars & Chemicals Ltd, Villupuram, Tamilnadu	Repair of 22 MW Skoda Make Turbine Rotor including, refining and Machining of Labyrinth Seals



# APT POWER ENGINEERING (P) LIMITED

( ISO 9001:2015 | OHSAS 45001:2018 | ISO 14001:2015 Certified Company)

Reg. Off / Works: Plot No: 11B, IDA, Phase-II, Patancheru, Hyderabad – 502319, T.S, INDIA.

114	M/s. Olam Global Agri Commodities India Private Limited, Kholapur	Polishing and machining of journals for 20.5 MW Generator
115	M/s. Tata Steels Ltd, Dhenkhannal, Odhisha	Refining of Oil & Air gland , Rebabitting & Machining of bearings for 77 MW BHEL make Generator
116	M/s.Shakambhari Ispat & Power Ltd, Purilia, West Bengal	Refining & Machining of Turbine rotor & Carriers for 8 MW Siemens make Turbine
117	M/s. Tata Steels Ltd, Dhenkhannal, Odhisha	Rebabitting & Machining of bearings for 12 MW BHEL make Generator
118	M/s.Shakambhari Ispat & Power Ltd, Purilia, West Bengal	Refining & Machining of Turbine rotor & Carriers for 8 MW TG#1 Siemens make Turbine
119	M/s.JSW Steel Ltd, Raigad	Repair & Refurbishment of 4.5 MW TRT & Generator, Rewinding of Exciter
120	M/s.JSW Steel Ltd, Bellary	Repair & Refurbishment of Shangu make Impeller Rotor
121	M/s. Ultratech Cement Ltd, Aditya Cement Works, Chitorgarh	Repair of Front oil Gland area on Turbine, Refining and Machining of HP Nozzle Block fins and Diaphragm Fins for 16 MW QJPS make Turbine
122	M/s.Shree Cement Ltd, RAS	Refining and machining of Turbine Rotor & Guide Blade carriers, Removal , Procurement and Assembly of Nozzle Block blades for 27 MW BHEL make Turbine
123	M/s. Topworth Urja Metals Ltd, Nagpur	Exciter armature and stator new core supply and complete re-winding of armature and stator for 30 MW Jinan make Generator Rotor
124	M/s. Mukand Ltd, Koppal	Refining & Machining of Nozzle block fins & Refilling of metal and Machining of Fins area for 15 MW QJPS Turbine
125	M/s.Meenakshi Energy Ltd, Nellore	Repair of HIP Rotor, Removal of LP Rotor Last stage blades , correction and assembly , Repair of IP carrier and Nozzle block for 150 MW Nanjing make Turbine



# APT POWER ENGINEERING (P) LIMITED

( ISO 9001:2015 | OHSAS 45001:2018 | ISO 14001:2015 Certified Company)

Reg. Off / Works: Plot No: 11B, IDA, Phase-II, Patancheru, Hyderabad – 502319, T.S, INDIA.

126	M.s, Rana Sugars Ltd,Rampur	Repair of LP Turbine Rotor & Generator Rotor for 27 MW Siemens make Turbine
127	M/s.GE Power India Ltd, Bangalore	Repair of 55 MW GE make Generator Rotor
128	M/s.JSW Steel Ltd, Dolvi, Maharastra	Repair of 36MW Nanyang make Generator Rotor
127	M/s.JSW Steel Ltd, Dolvi, Maharastra	Repair & Refurbishment 36 MW Shanghu make TRT Rotor & Guide Blade Carriers & Gland
128	M/s.Tulsyan Nec Limite, Gummidipoondi	Refining & Machining of Turbine Rotor Fins, Guide Blade Carriers & Steam Glands for 35 MW Siemens make TG Set
129	M/s. Topwoth Urja Metals Ltd, Nagpur	Refining & Machining of Turbine Rotor Fins, Guide Blade Carriers & Steam Glands & Oil glands & Rebitting of Bearings for 30 MW HTC make TG Set
130	M/s.GE Power India Ltd, Maharastra	Repair & Inspection of 250 MW IP Turbine Rotor
131	M/s.GE Power India Ltd, Noida	Pre Machining of Front and Rear Journals to remove pitting Marks, Metal build up by Laser beam welding , Machining and NDT Testing for 9.2 MW Turbine Rotor
132	M/s. Chettinad Cement Ltd, Gulbarga	Repair of Turbine Rotor Coupling area, welding and final machining of 7 MW QJPS make Turbine Rotor
133	M/s.Rajshree Sugars & Chemicals Ltd, Villupuram	Refining & Machining of Turbine Rotor Fins, Guide Blade Carriers & Steam Glands for 22 MW Skoda make TG Set
134	M/s.Westrock India Private Ltd,Vapi, Gujarat	Refining & Machining of Turbine Rotor Fins & Steam Glands for 20 MW SNM make TG Set
135	M/s.Ultratech Cement Ltd, Rajashree CeMENT Works, Gulbarga	Refining & Machining of Diaphragms, Nozzle Block & Oil Glands for 10 MW QJPS make Turbine



## APT POWER ENGINEERING (P) LIMITED

( ISO 9001:2015 | OHSAS 45001:2018 | ISO 14001:2015 Certified Company)

Reg. Off / Works: Plot No: 11B, IDA, Phase-II, Patancheru, Hyderabad – 502319, T.S, INDIA.

136	M/s. Dalmia Bharat Sugars Ltd, Sitapur	Repair of 25 MW Jinan make Generator Rotor
137.	M/s PT Sulzer, Indonesia	Repair of 330MW Turbine Rotor including NDT testing and high speed dynamic balancing of turbine rotor
138	M/s GE Power India Limited	Repair of 250MW Turbine Rotor including NDT testing, Refining and Machining of front, BP gland and Rear steam gland fins, removal of 17 stage blades, assembly and machining and high speed dynamic balancing of turbine rotor